

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including USACE Erosion Survey**

***Sacramento River Basin***

<b>RD0765</b>	Overall LMA Rating	Total LMA Miles				
<b>Reclamation District No. 0765 Glide</b>	<b>U</b>	<b>1.74</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.13	0.03	0.25	14.37%		
Trim / Thin Trees	0.63	0.20	1.43	82.18%		
Encroachments	0.01		0.01	0.58%	0.11	0.03
<i>LMA Totals:</i>	0.77	0.23	1.69	97.13%	0.11	0.03

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2010 Levee Inspection Results**

**Reclamation District No. 0765 Glide**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			U	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2010 Levee Inspection Results**

**Reclamation District No. 0765 Glide**

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	1.74
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	3/16/2010		9/21/2010	
DWR Inspector	Richard Willoughby		Richard Willoughby	
Accompanied By	Dave Chestnut RD765		Dave Chestnut RD765	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.11	Earthen Levee	Encroachments	LS	PO	Fences	38.502962 ° -121.560112 °	38.501373 ° -121.560402 °	12
2	0.05	0.05	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.502253 ° -121.560192 °	38.502253 ° -121.560192 °	3
3	0.09	0.09	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.501643 ° -121.560283 °	38.501643 ° -121.560283 °	27
4	0.12	0.19	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.501215 ° -121.560432 °	38.500271 ° -121.560434 °	28 Y
5	0.14	0.14	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.500928 ° -121.560431 °	38.500928 ° -121.560431 °	22
6	0.19	0.25	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.500343 ° -121.560507 °	38.499465 ° -121.560490 °	14
7	0.25	0.28	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.499405 ° -121.560445 °	38.499042 ° -121.560430 °	11 Y
8	0.32	0.32	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.498473 ° -121.560372 °	38.498473 ° -121.560372 °	26
9	0.41	0.41	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.497196 ° -121.560147 °	38.497196 ° -121.560147 °	21
10	0.41	0.47	Earthen Levee	Trim / Thin Trees	WS	C	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.497129 ° -121.560093 °	38.496320 ° -121.559802 °	23
11	0.43	0.47	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.496792 ° -121.560026 °	38.496321 ° -121.559842 °	32
12	0.48	0.50	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.496217 ° -121.559788 °	38.495855 ° -121.559586 °	33 Y
13	0.51	0.55	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.495648 ° -121.559391 °	38.495298 ° -121.559278 °	24
14	0.54	0.54	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.495347 ° -121.559291 °	38.495347 ° -121.559291 °	34
15	0.62	0.65	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.494468 ° -121.558577 °	38.494037 ° -121.558192 °	16
16	0.65	0.65	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.494097 ° -121.558192 °	38.494097 ° -121.558192 °	19
17	0.66	0.66	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.493917 ° -121.558041 °	38.493917 ° -121.558041 °	18
18	0.69	0.69	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.493596 ° -121.557832 °	38.493596 ° -121.557832 °	35
19	0.71	0.71	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.493392 ° -121.557640 °	38.493392 ° -121.557640 °	15

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
20	0.72	0.72	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.493201 ° -121.557526 °	38.493201 ° -121.557526 °	13
21	0.78	0.81	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.492392 ° -121.557026 °	38.492034 ° -121.556820 °	36
22	0.87	1.03	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.491283 ° -121.556360 °	38.489149 ° -121.555121 °	17 Y
23	0.95	0.98	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	38.490168 ° -121.555673 °	38.489864 ° -121.555520 °	25
24	0.99	1.05	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.489705 ° -121.555385 °	38.488990 ° -121.554993 °	8 Y
25	1.08	1.08	Earthen Levee	Trim / Thin Trees	LS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.488503 ° -121.554757 °	38.488503 ° -121.554757 °	37 Y
26	1.10	1.16	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.488279 ° -121.554615 °	38.487465 ° -121.554117 °	38
27	1.11	1.15	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.488108 ° -121.554488 °	38.487605 ° -121.554182 °	10
28	1.15	1.15	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.487653 ° -121.554248 °	38.487653 ° -121.554248 °	39 Y
29	1.16	1.16	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.487473 ° -121.554080 °	38.487473 ° -121.554080 °	9
30	1.19	1.22	Earthen Levee	Encroachments	LS	CO	Buildings	38.487127 ° -121.553910 °	38.486702 ° -121.553652 °	43 Y
31	1.31	1.35	Earthen Levee	Trim / Thin Trees	WS	C	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.485563 ° -121.553025 °	38.484978 ° -121.552660 °	40
32	1.36	1.36	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.484877 ° -121.552540 °	38.484877 ° -121.552540 °	7 Y
33	1.39	1.39	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.484543 ° -121.552276 °	38.484543 ° -121.552276 °	6
34	1.41	1.41	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.484316 ° -121.552115 °	38.484316 ° -121.552115 °	4
35	1.44	1.47	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.483925 ° -121.551845 °	38.483530 ° -121.551587 °	5 Y
36	1.46	1.46	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	38.483622 ° -121.551694 °	38.483622 ° -121.551694 °	41
37	1.50	1.50	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.483170 ° -121.551367 °	38.483170 ° -121.551367 °	42
38	1.54	1.60	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.482627 ° -121.551038 °	38.481810 ° -121.550538 °	20

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated	C : Corrected W : Watch/Monitor
--	--	--	------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway						Bank	Unit Miles	Inspection Start/End		Inspector
Unit No. 01 Sacramento River						Right	1.74	10/13/2010 10/13/2010		Richard Willoughby
LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
39	1.54	1.54	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.482590 ° -121.551020 °	38.482590 ° -121.551020 °	29 Y
40	1.60	1.67	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.480913 ° -121.549677 °	38.480993 ° -121.549738 °	2 Y
41	1.60	1.60	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.481841 ° -121.550438 °	38.482028 ° -121.550512 °	31
42	1.69	1.69	Earthen Levee	Encroachments	WS	M	Garbage	38.480770 ° -121.549514 °	38.480895 ° -121.549556 °	30 Y
43	1.70	1.73	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.480602 ° -121.549523 °	38.480257 ° -121.549458 °	1 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	4
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking west at trees on landside toe.

richard\_f\_20100921\_219.jpg



Levee Mile Report Line	4
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking downstream (south) at trees on landside slope & toe.

richard\_f\_20100921\_220.jpg



Levee Mile Report Line	7
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking northeast at overgrown trees on waterside slope.

richard\_f\_20100921\_214.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	7
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking north at overgrown trees on waterside slope.

richard\_f\_20100921\_215.jpg



Levee Mile Report Line	12
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking northwest at trees on landside toe.

richard\_f\_20100921\_225.jpg



Levee Mile Report Line	12
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (south) at trees on landside slope & toe.

richard\_f\_20100921\_226.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	22
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking downstream (south) at trees on landside slope & toe.

richard\_f\_20100921\_216.jpg



Levee Mile Report Line	22
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking west at trees and vines on landside toe.

richard\_f\_20100921\_217.jpg



Levee Mile Report Line	22
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (northwest) at trees on landside slope & toe.

richard\_f\_20100921\_218.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	24
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking northeast at trees on waterside slope.

richard\_f\_20100921\_212.jpg



Levee Mile Report Line	24
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at trees on waterside slope.

richard\_f\_20100921\_213.jpg



Levee Mile Report Line	25
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking downstream (south) at trees on landside slope & toe.

richard\_f\_20100921\_227.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	25
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking west at trees on landside slope & toe.

richard\_f\_20100921\_228.jpg



Levee Mile Report Line	28
Start Levee Mile	1.15
End Levee Mile	1.15
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (southwest) at wild roses on landside slope & toe.

richard\_f\_20100921\_229.jpg



Levee Mile Report Line	30
Start Levee Mile	1.19
End Levee Mile	1.22
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Looking northwest at buildings along landside toe.

richard\_f\_20101014\_330.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	32
Start Levee Mile	1.36
End Levee Mile	1.36
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking southeast (downstream) at trees on waterside slope.

richard\_f\_20100921\_211.jpg



Levee Mile Report Line	35
Start Levee Mile	1.44
End Levee Mile	1.47
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at trees on waterside slope.

richard\_f\_20100921\_208.jpg



Levee Mile Report Line	35
Start Levee Mile	1.44
End Levee Mile	1.47
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking east at trees on waterside slope.

richard\_f\_20100921\_209.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	39
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (southwest) at trees, vines & wildroses on landside slope & toe.

richard\_f\_20100921\_221.jpg



Levee Mile Report Line	39
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (south) at trees, vines & wildroses on landside slope & toe.

richard\_f\_20100921\_222.jpg



Levee Mile Report Line	40
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking east at trees on waterside slope.

richard\_f\_20100921\_206.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	40
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at trees on waterside slope.

richard\_f\_20100921\_207.jpg



Levee Mile Report Line	42
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Looking upstream at garbage on waterside slope.

richard\_f\_20100921\_223.jpg



Levee Mile Report Line	42
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Looking downstream at garbage on waterside slope.

richard\_f\_20100921\_224.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2010**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/13/2010 10/13/2010	Richard Willoughby

Levee Mile Report Line	42
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments

District manager has stack garbage on shoulder to be haul away. (Looking north)

richard\_f\_20101014\_329.jpg



Levee Mile Report Line	43
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at trees on waterside slope.

richard\_f\_20100921\_204.jpg



Levee Mile Report Line	43
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking east at trees on waterside slope.

richard\_f\_20100921\_205.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor